# **Limited Asbestos Assessment**

# **Newhart Middle School**

25001 Veterans Way, Building 300, Southeast and Northwest Roofs

City of Mission Viejo County of Orange State of California

Project Number: Atch-230586

February 21, 2023



**Prepared For:** 

# **Capistrano Unified School District**

**PRIVILEGED & CONFIDENTIAL** 



CALIFORNIA • OREGON • WASHINGTON • NEVADA • ARIZONA • TEXAS

#### Cover

# ASBESTOS

## **Table of Contents**

# I. Executive Summary

- 1.0 Introduction
- 2.0 Scope of Assessment
- 3.0 Previous Assessment/Historical Data
- 4.0 Visual Inspection and Sampling/Analytical Methodology
- 5.0 Laboratory Accreditation and Analytical Procedures
- 6.0 Building Condition
- 7.0 Asbestos Identification
- 8.0 Recommendations
- 9.0 Limitations

## **II. Appendices**

- A. Asbestos Bulk Sample Analysis
- B. Floor Plans: Asbestos Bulk Sample Locations

C. Laboratory Reports-Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method Using Polarized Light Microscopy and Chain of Custody

D. Inspector Certifications

Atch-230586 Limited Asbestos Assessment 25001 Veterans Way Mission Viejo, California 92692

February 21, 2023

Capistrano Unified School District 32972 Calle Perfecto San Juan Capistrano, California 92675

Attn: Mr. Steve Matteson, Jr.

Re: Newhart Middle School 25001 Veterans Way, Building 300, Southeast and Northwest Roofs Mission Viejo, California 92692

Pursuant to your request, A-Tech Consulting, Inc. (A-Tech) has completed a Limited Asbestos Assessment of Building 300, Southeast and Northwest Roofs at Newhart Middle School at 25001 Veterans Way in Mission Viejo, California. The following report summarizes the findings of this inspection. Please direct all questions for this project to A-Tech's CSST or CAC who performed the sampling at (800) 434-1025 or pm@atechinc.net.

## **1.0 INTRODUCTION**

A-Tech was contacted by Mr. Steve Matteson, Jr. with Capistrano Unified School District to confirm the presence or absence of asbestos in Building 300, Southeast and Northwest Roofs of Newhart Middle School located at 25001 Veterans Way (subject property), in Mission Viejo, California. The assessment was conducted by Lloyd Hernandez Tangunan - CAC #05-3891 with A-Tech on February 16, 2023. This report is not intended to be a comprehensive assessment.

#### 2.0 SCOPE OF ASSESSMENT

The limited asbestos assessment was performed to identify visible and/or readily accessible suspect friable and non-friable Asbestos Containing Building Materials (ACBMs) at a subject property. The intent of this assessment was to satisfy all regulatory requirements for renovation and/or demolition. Friable ACM, as defined by the U.S. Environmental Protection Agency (EPA) and South Coast Air Quality Management District (SCAQMD), Rule 1403, is a material that, when dry, can be easily pulverized, crushed or reduced to powder by hand pressure. Non-friable ACBM that can potentially be broken, crumbled, pulverized or reduced to powder in the course of demolition or renovation activities are classified as Category I or Category II, non-friable ACBM. These assessments are typically accomplished by, and limited to, an in-depth site reconnaissance, a review of readily available building records, and a review of readily available asbestos operation and maintenance (O&M) plans. In the event that suspected or known ACBMs exist at a given site, samples of the potential ACBMs may be collected for subsequent laboratory analysis.

This inspection was limited to representative locations in the project area that may be affected by the renovation activities. Limited intrusive and/or non-destructive sampling was conducted as a part of the scope of services performed. If additional suspect materials are observed by the contractor, abatement contractor, building owner and/or its representatives, A-Tech should be notified to conduct additional testing. Certain materials may not have been visible/accessible during the initial assessment such as subsurface materials, live electrical equipment, materials in pipe chases, barrier paper under wood, sub-slab membranes, materials under the building structure, in wall and ceiling cavities, etc.

This Limited Asbestos Assessment was conducted in accordance with the scope of services authorized by Mr. Steve Matteson, Jr. with Capistrano Unified School District in accordance with current regulatory guidelines.

# 3.0 PREVIOUS ASSESSMENT/HISTORICAL DATA

No prior asbestos related documentation for the subject property was reviewed or made available.

#### 4.0 VISUAL INSPECTION AND SAMPLING/ANALYTICAL METHODOLOGY

To identify suspect friable and non-friable ACBM, as required under California law, a California Occupational Safety Health Administration (CAL-OSHA) Certified Site Surveillance Technician (CSST) and/or Certified Asbestos Consultant (CAC) is required to conduct visual and/or bulk assessments of a subject property.

During this assessment, A-Tech identified homogenous areas of suspected ACBMs for purpose of sampling in accordance with current CAL-OSHA/EPA (AHERA) requirements. These areas were defined with respect to similarities in appearance, age, use, type, color, and/or texture. The condition and estimated quantity of the suspected materials were also assessed. Based upon A-Tech observations, eight (8) homogeneous suspect asbestos containing building materials were identified. Only pre-selected materials delineated by Capistrano Unified School District were sampled during this inspection. Please refer to Appendix A for a complete list of sampled materials.

To evaluate the presence of asbestos in these suspected ACBMs, A-Tech Consulting, Inc. obtained twenty-eight (28) bulk samples, which appeared to represent each homogeneous area (see tables). However, some of the samples analyzed may have multiple layers of material, which the laboratory is required to separate and analyze independently. The total amount of samples analyzed was seventy-seven (77). Regarding multiple layered materials, if one layer tests positive for asbestos content, the entire sample is considered positive.

Whenever possible A-Tech does not conduct destructive sampling (with the exception of vacant buildings to be demolished). For example, samples of floor tile were collected by taking a small chip out of a corner or area that was already damaged.

After collecting each sample, the sampling equipment was cleaned with a moist towelette. Each sample was sealed in a sample container and assigned a discrete sample identification number.

## 5.0 LABORATORY ACCREDITATION & ANALYTICAL PROCEDURES

The twenty-eight (28) samples obtained from the subject property were delivered to Eurofins EPK Built Environment Testing, LLC located at 2841 Dow Avenue, Suite 300, Tustin, California 92780 (866) 888-6653 (under chain-of-custody procedures) for analysis. This Laboratory is a fully accredited laboratory by the National Institute of Standards and Technology (NIST) through participation in the National Voluntary Laboratory Accreditation Program (NVLAP) lab code #200757-0.

The samples were analyzed for asbestos by PLM, using dispersion staining in accordance with U.S. EPA Procedures outlined in 40 CFR 763, Subpart F, Appendix A (AHERA). Utilizing the PLM 600R/R-93/116 method, the result given is a semi-quantitative result (down to <1%) which reflects a calibrated visual estimate from an analyst using both Polarized Light Microscopy and Stereomicroscopy.

#### 6.0 BUILDING CONDITION

Per our visual observation, the facility structure appears to be in good condition with no structural damage.

#### 7.0 ASBESTOS IDENTIFICATION

Based upon the analytical results, asbestos is not present in the materials analyzed.

#### 8.0 RECOMMENDATIONS

No recommendations are made at this time for the areas and materials sampled. However, this was not a comprehensive assessment of the building and any impact of materials or areas not assessed would require additional sampling.

#### 9.0 LIMITATIONS

The conclusions presented in this report are professional opinions based solely upon visual observations at the site and laboratory analysis of the tested samples. They are intended exclusively for the purpose outlined herein, and for the site location and project indicated.

This assessment report is not specifications for asbestos abatement and it should not be used as a stand-alone asbestos abatement bid document. Recognizing that even the most comprehensive assessment may fail to detect ACBM at a particular site, this study was not intended to identify all potential ACBM present in the building or at the site for such reasons as the possible existence of buried, covered and inaccessible areas and features. A-Tech does not warrant that all sub-surface, wall cavity or other inaccessible materials were tested. A-Tech did not test any live electrical components or disassemble operational building equipment such as fans or HVAC components. These components may contain untested suspect ACBM's. If any suspect ACBMs not tested herein are discovered, they must be tested prior to impact.

A-Tech assumes no responsibility for the identification of suspect asbestos containing materials, which are not included in this assessment, concealed and/or inaccessible (i.e. locked rooms, under carpet, etc.) However, A-Tech makes every attempt possible to inspect all designated areas for asbestos containing materials (i.e. check under carpeting, inspect attic, crawl space, etc.).

Services performed by A-Tech were conducted in a manner above the care and skill ordinarily and currently exercised by members of the same profession that even the most comprehensive scope of services might fail to detect environmental liabilities on a particular site. Therefore, A-Tech cannot act as insurers and cannot "certify" that a site is free of environmental contamination.

No expressed or implied representation or warranty is included or intended in our reports, except that our services were performed, within the limits prescribed by the Scope of Services, with the customary thoroughness and competence of our profession.

This report is intended for the sole use of the contracted Client and its authorized representatives. The exchange of information was unique between A-Tech and the client regarding the mutually agreed upon scope of service. Unless explicitly authorized in this report, no third party is beneficiary to the contract or findings of this report. The unauthorized use or reliance of this document or the findings, conclusion or recommendations presented herein, by any other party or parties is at the sole risk of any such third party. For the same reasons, no warranties or representations, expressed or implied in this report, are provided to any such third party.

Information and opinions presented herein apply to the existing and reasonable foreseeable site conditions at the time of our investigation. They cannot necessarily apply to site changes of which this office is unaware and have not had the opportunity to review. Changes in the conditions of this property may occur with time due to natural processes or works of man on the subject property or on adjacent properties. Changes in applicable standards may also occur as a result of legislation or the broadening of knowledge. Accordingly, the findings of this report may be invalidated, wholly or in part by changes beyond our control.

A-Tech trusts that the information presented herein provides the data you require. Should you have any questions or comments please contact A-Tech Consulting, Inc. at (800) 434-1025.

Respectfully submitted,

A-Tech Consulting, Inc.

Mmt 2

Robert L. Williams, DPH, CAC, CIEC Certified Asbestos Consultant #96-1980



# **Asbestos Bulk Analysis**

Location: Newhart Middle School, 25001 Veterans Way

Area: Building 300, Southeast and Northwest Roofs

Sample Asbestos Type -**Sample Location** Material Pos/Neg Classification Friability Cond. Est. Qty. Access. Number Percentage 300, Roof, Southeast Bldg., Roof, West Build-up Roofing Core Negative 230586-A-001A None Detected N/A N/A N/A N/A N/A Side 300, Roof, Southeast Bldg., Roof, South 230586-A-001B Build-up Roofing Core Negative None Detected N/A N/A N/A N/A N/A Side 300, Roof, Southeast Bldg., Roof, North 230586-A-001C Build-up Roofing Core Negative None Detected N/A N/A N/A N/A N/A Side 300, Roof, Southeast Bldg., Roof, 230586-A-001D Build-up Roofing Core Negative None Detected N/A N/A N/A N/A N/A Northeast Side 300, Roof, Southeast Bldg., Roof, 230586-A-001E Build-up Roofing Core Negative None Detected N/A N/A N/A N/A N/A Southeast Side Parapet Wall - Build-up Bldg. 300, Roof, Southeast Bldg., Roof, 230586-A-002A Negative None Detected N/A N/A N/A N/A N/A West Parapet Wall Roofing Bldg. 300, Roof, Southeast Bldg., Roof, Parapet Wall - Build-up 230586-A-002B Negative None Detected N/A N/A N/A N/A N/A Roofing South Parapet Wall Parapet Wall - Build-up Bldg. 300, Roof, Southeast Bldg., Roof, 230586-A-002C Negative None Detected N/A N/A N/A N/A N/A Roofing East Parapet Wall Bldg. 300, Roof, Southeast Bldg., Roof, 230586-A-003A **Roof Penetration Mastic** Negative None Detected N/A N/A N/A N/A N/A Northwest Side Bldg. 300, Roof, Southeast Bldg., Roof, 230586-A-003B **Roof Penetration Mastic** Negative None Detected N/A N/A N/A N/A N/A South Side Bldg. 300, Roof, Southeast Bldg., Roof, 230586-A-003C **Roof Penetration Mastic** Negative None Detected N/A N/A N/A N/A N/A Northeast Side


Client Name: Capistrano Unified School District




<u>Sample</u> <u>Number</u>	<u>Material</u>	Sample Location	Pos/Neg	<u>Asbestos Type -</u> <u>Percentage</u>	<u>Classification</u>	<u>Friability</u>	<u>Cond.</u>	<u>Access.</u>	<u>Est. Qty.</u>
230586-A-004A	Flashing Mastic	Bldg. 300, Roof, Southeast Bldg., Roof, West Edge of Roof	Negative	None Detected	N/A	N/A	N/A	N/A	N/A
230586-A-004B	Flashing Mastic	Bldg. 300, Roof, Southeast Bldg., Roof, South Edge Of Roof	Negative	None Detected	N/A	N/A	N/A	N/A	N/A
230586-A-004C	Flashing Mastic	Bldg. 300, Roof, Southeast Bldg., Roof, East Edge of Roof	Negative	None Detected	N/A	N/A	N/A	N/A	N/A
230586-A-005A	Build-up Roofing Core	Bldg. 300, Roof, Northwest Bldg., Roof, Southwest Side	Negative	None Detected	N/A	N/A	N/A	N/A	N/A
230586-A-005B	Build-up Roofing Core	Bldg. 300, Roof, Northwest Bldg., Roof, Southeast Side	Negative	None Detected	N/A	N/A	N/A	N/A	N/A
230586-A-005C	Build-up Roofing Core	Bldg. 300, Roof, Northwest Bldg., Roof, Northeast Side	Negative	None Detected	N/A	N/A	N/A	N/A	N/A
230586-A-005D	Build-up Roofing Core	Bldg. 300, Roof, Northwest Bldg., Roof, Northwest Side	Negative	None Detected	N/A	N/A	N/A	N/A	N/A
230586-A-005E	Build-up Roofing Core	Bldg. 300, Roof, Northwest Bldg., Roof, North Side	Negative	None Detected	N/A	N/A	N/A	N/A	N/A
230586-A-006A	Parapet Wall - Build-up Roofing	Bldg. 300, Roof, Northwest Bldg., Roof, North Parapet Wall	Negative	None Detected	N/A	N/A	N/A	N/A	N/A
230586-A-006B	Parapet Wall - Build-up Roofing	Bldg. 300, Roof, Northwest Bldg., Roof, West Side	Negative	None Detected	N/A	N/A	N/A	N/A	N/A
230586-A-006C	Parapet Wall - Build-up Roofing	Bldg. 300, Roof, Northwest Bldg., Roof, South Parapet Wall	Negative	None Detected	N/A	N/A	N/A	N/A	N/A
230586-A-007A	Roof Penetration Mastic	Bldg. 300, Roof, Northwest Bldg., Roof, South Side	Negative	None Detected	N/A	N/A	N/A	N/A	N/A
230586-A-007B	Roof Penetration Mastic	Bldg. 300, Roof, Northwest Bldg., Roof, West Side	Negative	None Detected	N/A	N/A	N/A	N/A	N/A



<u>Sample</u> <u>Number</u>	<u>Material</u>	Sample Location	Pos/Neg	<u>Asbestos Type -</u> <u>Percentage</u>	<u>Classification</u>	<u>Friability</u>	<u>Cond.</u>	<u>Access.</u>	<u>Est. Qty.</u>
230586-A-007C	Roof Penetration Mastic	Bldg. 300, Roof, Northwest Bldg., Roof, Northwest Side	Negative	None Detected	N/A	N/A	N/A	N/A	N/A
230586-A-008A	Flashing Mastic	Bldg. 300, Roof, Northwest Bldg., Roof, Northwest Roof Edge	Negative	None Detected	N/A	N/A	N/A	N/A	N/A
230586-A-008B	Flashing Mastic	Bldg. 300, Roof, Northwest Bldg., Roof, West Roof Edge	Negative	None Detected	N/A	N/A	N/A	N/A	N/A
230586-A-008C	Flashing Mastic	Bldg. 300, Roof, Northwest Bldg., Roof, Southwest Roof Edge	Negative	None Detected	N/A	N/A	N/A	N/A	N/A





Not to Scale	

	A-04C	Α	-02C	
			A-01E	
A-01D				
			E	A 04P
A-03C			Ľ	A-04B
			-	
				A-02B
		A	-03B	
A-01C				
A-OTC			A-01B	
A-03A				
L.	A-01A			
-				_
		A-02A	A-04	A

# Building 300, Roof(Southeast)

Floor Plan - Asbestos - Page 2 of 2

Newhart Middle School 25001 Veterans Way Mission Viejo, California 92692

LEGEND: A = Positive Asbestos Sample Locations A = Negative Asbestos Sample Locations

Project #: Atch- 230586

Capistrano Unified School District



**Built Environment Testing** 

Report for:

Mr. Robert Williams A-Tech Consulting, Inc 1640 N. Batavia Street Orange, CA 92867

Regarding: Eurofins EPK Built Environment Testing, LLC Project: 230586; 25001 Veterans Way Missions Viejo CA EML ID: 3170054

Approved by:

Approved Signatory Danny Li

Dates of Analysis: Asbestos PLM: 02-18-2023

Service SOPs: Asbestos PLM (EPA 40CFR App E to Sub E of Part 763 & EPA METHOD 600/R-93-116, SOP EM-AS-S-1267) NVLAP Lab Code 200757-0

All samples were received in acceptable condition unless noted in the Report Comments portion in the body of the report. The results relate only to the samples as received and tested. The results include an inherent uncertainty of measurement associated with estimating percentages by polarized light microscopy. Measurement uncertainty data for sample results with >1% asbestos concentration can be provided when requested.

Eurofins EPK Built Environment Testing, LLC ("the Company"), a member of the Eurofins Built Environment Testing group of companies, shall have no liability to the client or the client's customer with respect to decisions or recommendations made, actions taken or courses of conduct implemented by either the client or the client's customer as a result of or based upon the Test Results. In no event shall the Company be liable to the client with respect to the Test Results except for the Company's own willful misconduct or gross negligence nor shall the Company be liable for incidental or consequential damages or lost profits or revenues to the fullest extent such liability may be disclaimed by law, even if the Company has been advised of the possibility of such damages, lost profits or lost revenues. In no event shall the Company's liability with respect to the Test Results exceed the amount paid to the Company by the client therefor.

# **Eurofins EPK Built Environment Testing, LLC**

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (866) 888-6653 www.eurofinsus.com/Built

Client: A-Tech Consulting, Inc C/O: Mr. Robert Williams Date of Receipt: 02-17-2023 Re: 230586; 25001 Veterans Way Missions Viejo CADate of Report: 02-20-2023

# Summary of Samples with Asbestos Detected

Total Samples Submitted:	28
Total Samples Analyzed:	28
Total Layers Analyzed:	77
Total Samples with Layer Asbestos Content > 1%:	0
Total Samples with Layer Asbestos Content < 1%:	0

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

Client: A-Tech Consulting, Inc C/O: Mr. Robert Williams Date of Receipt: 02-17-2023 Re: 230586; 25001 Veterans Way Missions Viejo CADate of Report: 02-20-2023

# **ASBESTOS PLM REPORT**

Location: 230586-A-001A, 300 Roof, Southeast Bldg., R	oof, Build-Up Roofing Core	Lab ID-Version‡: 15338404-1
Sample Layers	Asbestos Cor	ntent
White Coating	ND	
Black Roofing Shingle with Pebbles	ND	
Black Roofing Tar and Felt 1	ND	
Black Roofing Tar and Felt 2	ND	
Black Roofing Tar and Felt 3	ND	
Composite Non-Asbestos Content:	<ul><li>15% Glass Fibers</li><li>10% Synthetic Fibers</li></ul>	
Sample Composite Homogeneity:	Poor	

#### Location: 230586-A-001B, 300 Roof, Southeast Bldg., Roof, Build-Up Roofing Core

Sample Layers	Asbestos Content
White Coating	ND
Black Roofing Shingle with Pebbles	ND
Black Roofing Tar and Felt 1	ND
Black Roofing Tar and Felt 2	ND
Black Roofing Tar and Felt 3	ND
Composite Non-Asbestos Content:	15% Glass Fibers 10% Synthetic Fibers
Sample Composite Homogeneity:	Poor

#### Location: 230586-A-001C, 300 Roof, Southeast Bldg., Roof, Build-Up Roofing Core

Sample Layers	Asbestos Content
White Coating	ND
Black Roofing Shingle with Pebbles	ND
Black Roofing Tar and Felt 1	ND
Black Roofing Tar and Felt 2	ND
Black Roofing Tar and Felt 3	ND
Composite Non-Asbestos Content:	15% Glass Fibers 10% Synthetic Fibers
Sample Composite Homogeneity:	Poor

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

 $\ddagger$  A "Version" indicated by -"x" after the Lab ID# with a value greater than 1 indicates a sample with amended data. The revision number is reflected by the value of "x".

Eurofins EPK Built Environment Testing, LLC

Lab ID-Version 15338405-1

Lab ID-Version 15338406-1

Client: A-Tech Consulting, Inc C/O: Mr. Robert Williams Re: 230586; 25001 Veterans Way Missions Viejo CADate of Report: 02-20-2023

# **ASBESTOS PLM REPORT**

Location: 230586-A-001D, 300 Roof, Southeast Bldg., R	oof, Build-Up Roofing Core	Lab ID-Version‡: 15338407-1
Sample Layers	Asbestos Con	itent
White Coating	ND	
Black Roofing Shingle with Pebbles	ND	
Black Roofing Tar and Felt 1	ND	
Black Roofing Tar and Felt 2	ND	
Black Roofing Tar and Felt 3	ND	
Composite Non-Asbestos Content:	<ul><li>15% Glass Fibers</li><li>10% Synthetic Fibers</li></ul>	
Sample Composite Homogeneity:	Poor	

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

 $\ddagger$  A "Version" indicated by -"x" after the Lab ID# with a value greater than 1 indicates a sample with amended data. The revision number is reflected by the value of "x".

Client: A-Tech Consulting, Inc C/O: Mr. Robert Williams Date of Receipt: 02-17-2023 Re: 230586; 25001 Veterans Way Missions Viejo CADate of Report: 02-20-2023

# **ASBESTOS PLM REPORT**

Location: 230586-A-001E, 300 Roof, Southeast Bldg., R	oof, Build-Up Roofing Core Lat	b ID-Version‡: 15338408-1
Sample Layers	Asbestos Content	
White Coating	ND	
Black Roofing Shingle with Pebbles	ND	
Black Roofing Tar and Felt 1	ND	
Black Roofing Tar and Felt 2	ND	
Black Roofing Tar and Felt 3	ND	
Composite Non-Asbestos Content:	<ul><li>15% Glass Fibers</li><li>10% Synthetic Fibers</li></ul>	
Sample Composite Homogeneity:	Poor	

#### Location: 230586-A-002A, Bldg. 300, Roof, Southeast Bldg., Roof, Parapet Wall-Build-Up Roofing

Up Roofing	Lab ID-Version‡: 15338409-1
Sample Layers	Asbestos Content
White Coating	ND
Black Roofing Shingle with Pebbles	ND
Black Roofing Tar	ND
Composite Non-Asbestos Content:	
	10% Synthetic Fibers
Sample Composite Homogeneity:	Poor

#### Location: 230586-A-002B, Bldg. 300, Roof, Southeast Bldg., Roof, Parapet Wall-Build-Up Lab ID-Version<sup>‡</sup>: 15338410-1

Roofing

· .
Asbestos Content
ND
ND
ND
15% Glass Fibers
10% Synthetic Fibers
Poor

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

 $\ddagger$  A "Version" indicated by -"x" after the Lab ID# with a value greater than 1 indicates a sample with amended data. The revision number is reflected by the value of "x".

Client: A-Tech Consulting, Inc C/O: Mr. Robert Williams Date of Receipt: 02-17-2023 Re: 230586; 25001 Veterans Way Missions Viejo CADate of Report: 02-20-2023

## **ASBESTOS PLM REPORT**

Location: 230586-A-002C, Bldg. 300, Roof, Southeast Bldg., Roof, Parapet Wall-Build-Up Roofing

Up Roofing	Lab ID-Version‡: 15338411-1
Sample Layers	Asbestos Content
White Coating	ND
Black Roofing Shingle with Pebbles	ND
Black Roofing Tar	ND
Composite Non-Asbestos Content:	15% Glass Fibers 10% Synthetic Fibers
Sample Composite Homogeneity:	Poor

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

 $\ddagger$  A "Version" indicated by -"x" after the Lab ID# with a value greater than 1 indicates a sample with amended data. The revision number is reflected by the value of "x".

Client: A-Tech Consulting, Inc C/O: Mr. Robert Williams Re: 230586; 25001 Veterans Way Missions Viejo CADate of Report: 02-20-2023

## ASBESTOS PLM REPORT

# Location: 230586-A-003A, Bldg. 300, Roof, Southeast Bldg., Roof, Roof Penetration Mastic

Sample Layers	Asbestos Content
Gray/Black Roofing Mastic	ND
Composite Non-Asbestos Content:	10% Cellulose
Sample Composite Homogeneity:	Good

Location: 230586-A-003B, Bldg. 300, Roof, Southeast Bldg., Roof, Roof Penetration Mastic

Lab ID-Version 15338413-1

Lab ID-Version 15338412-1

Sample Layers	Asbestos Content
Gray/Black Roofing Mastic	ND
Composite Non-Asbestos Content:	10% Cellulose
Sample Composite Homogeneity:	Good

# Location: 230586-A-003C, Bldg. 300, Roof, Southeast Bldg., Roof, Roof Penetration Mastic

 Mastic
 Lab ID-Version‡: 15338414-1

 Sample Layers
 Asbestos Content

 Gray/Black Roofing Mastic
 ND

 Composite Non-Asbestos Content:
 10% Cellulose

 Sample Composite Homogeneity:
 Good

#### Location: 230586-A-004A, Bldg. 300, Roof, Southeast Bldg., Roof, Flashing Mastic Lab ID-Version 1: 15338415-1

Sample Layers	Asbestos Content
White Roofing Mastic	ND
Composite Non-Asbestos Content:	5% Glass Fibers
Sample Composite Homogeneity:	Moderate

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

A "Version" indicated by -"x" after the Lab ID# with a value greater than 1 indicates a sample with amended data. The revision number is reflected by the value of "x".

Client: A-Tech Consulting, Inc C/O: Mr. Robert Williams Date of Receipt: 02-17-2023 Re: 230586; 25001 Veterans Way Missions Viejo CA Date of Report: 02-20-2023

## ASBESTOS PLM REPORT

Location: 230586-A-004B, Bldg. 300, Roof, Southeast Bldg., Roof, Flashing Mastic Lab ID-Version 1: 15338	
Sample Layers	Asbestos Content
White Roofing Mastic	ND
Composite Non-Asbestos Content:	5% Glass Fibers
Sample Composite Homogeneity:	Moderate

#### Location: 230586-A-004C, Bldg. 300, Roof, Southeast Bldg., Roof, Flashing Mastic Lab ID-Version 15338417-1

Sample Layers	Asbestos Content
White Roofing Mastic	ND
Composite Non-Asbestos Content:	5% Glass Fibers
Sample Composite Homogeneity:	Moderate

# Location: 230586-A-005A, Bldg. 300, Roof, Northwest Bldg., Roof, Build-Up Roofing Core

Core	Lab ID-Version‡: 15338418-1
Sample Layers	Asbestos Content
White Coating	ND
Black Roofing Shingle with Pebbles	ND
Black Roofing Tar and Felt 1	ND
Black Roofing Tar and Felt 2	ND
Black Roofing Tar and Felt 3	ND
Composite Non-Asbestos Contents	15% Glass Fibers
	10% Synthetic Fibers
Sample Composite Homogeneity	Poor

# Location: 230586-A-005B, Bldg. 300, Roof, Northwest Bldg., Roof, Build-Up Roofing Core

Lab ID-Version<sup>‡</sup>: 15338419-1

Core	
Sample Layers	Asbestos Content
White Coating	ND
Black Roofing Shingle with Pebbles	ND
Black Roofing Tar and Felt 1	ND
Black Roofing Tar and Felt 2	ND
Black Roofing Tar and Felt 3	ND
Composite Non-Asbestos Content:	15% Glass Fibers 10% Synthetic Fibers
Sample Composite Homogeneity:	Poor

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

A "Version" indicated by -"x" after the Lab ID# with a value greater than 1 indicates a sample with amended data. The revision number is reflected by the value of "x".

Client: A-Tech Consulting, Inc C/O: Mr. Robert Williams Re: 230586; 25001 Veterans Way Missions Viejo CADate of Report: 02-20-2023

# **ASBESTOS PLM REPORT**

Location: 230586-A-005C, Bldg. 300, Roof, Northwest Bldg., Roof, Build-Up Roofing Core

	···· ··· ··· ··· ··· ··· ··· ··· ··· ·
Sample Layers	Asbestos Content
White Coating	ND
Black Roofing Shingle with Pebbles	ND
Black Roofing Tar and Felt 1	ND
Black Roofing Tar and Felt 2	ND
Black Roofing Tar and Felt 3	ND
Composite Non-Asbestos Content:	15% Glass Fibers
-	10% Synthetic Fibers
Sample Composite Homogeneity:	Poor

# Location: 230586-A-005D, Bldg. 300, Roof, Northwest Bldg., Roof, Build-Up Roofing Core

Lab ID-Version #: 15338421-1

Lab ID-Version<sup>‡</sup>: 15338420-1

	•
Sample Layers	Asbestos Content
White Coating	ND
Black Roofing Shingle with Pebbles	ND
Black Roofing Tar and Felt 1	ND
Black Roofing Tar and Felt 2	ND
Black Roofing Tar and Felt 3	ND
Composite Non-Asbestos Content:	<ul><li>15% Glass Fibers</li><li>10% Synthetic Fibers</li></ul>
Sample Composite Homogeneity:	Poor

# Location: 230586-A-005E, Bldg. 300, Roof, Northwest Bldg., Roof, Build-Up Roofing Core

Lab ID-Version<sup>‡</sup>: 15338422-1

	Lao ID- version <sub>4</sub> . 15556422-1
Sample Layers	Asbestos Content
White Coating	ND
Black Roofing Shingle with Pebbles	ND
Black Roofing Tar and Felt 1	ND
Black Roofing Tar and Felt 2	ND
Black Roofing Tar and Felt 3	ND
Composite Non-Asbestos Content:	15% Glass Fibers 10% Synthetic Fibers
Sample Composite Homogeneity:	Poor

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

A "Version" indicated by -"x" after the Lab ID# with a value greater than 1 indicates a sample with amended data. The revision number is reflected by the value of "x".

Lab ID-Version 15338423-1

Client: A-Tech Consulting, Inc C/O: Mr. Robert Williams Date of Receipt: 02-17-2023 Re: 230586; 25001 Veterans Way Missions Viejo CADate of Report: 02-20-2023

## **ASBESTOS PLM REPORT**

Location: 230586-A-006A, Bldg. 300, Roof, Northwest Bldg., Roof, Parapet Wall-Build-Up Roofing

Sample Layers	Asbestos Content
Black Roofing Shingle with Pebbles	ND
Black Roofing Tar	ND
Composite Non-Asbestos Content:	15% Glass Fibers
Sample Composite Homogeneity:	Poor

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

A "Version" indicated by -"x" after the Lab ID# with a value greater than 1 indicates a sample with amended data. The revision number is reflected by the value of "x".

Client: A-Tech Consulting, Inc C/O: Mr. Robert Williams Date of Receipt: 02-17-2023 Re: 230586; 25001 Veterans Way Missions Viejo CADate of Report: 02-20-2023

# ASBESTOS PLM REPORT

#### Location: 230586-A-006B, Bldg. 300, Roof, Northwest Bldg., Roof, Parapet Wall-Build-Up Roofing

Sample Layers	Asbestos Content
Black Roofing Shingle with Pebbles	ND
Black Roofing Tar	ND
Composite Non-Asbestos Content:	15% Glass Fibers
Sample Composite Homogeneity:	Poor

#### Location: 230586-A-006C, Bldg. 300, Roof, Northwest Bldg., Roof, Parapet Wall-Build-Up Roofing

 Sample Layers
 Asbestos Content

 Black Roofing Shingle with Pebbles
 ND

 Black Roofing Tar
 ND

 Composite Non-Asbestos Content:
 15% Glass Fibers

 Sample Composite Homogeneity:
 Poor

# Location: 230586-A-007A, Bldg. 300, Roof, Northwest Bldg., Roof, Roof Penetration Mastic

Lab ID-Version<sup>‡</sup>: 15338426-1

Lab ID-Version 15338425-1

Lab ID-Version<sup>‡</sup>: 15338424-1

Sample Layers	Asbestos Content
Black Roofing Mastic	ND
Sample Composite Homogeneity:	Good

# Location: 230586-A-007B, Bldg. 300, Roof, Northwest Bldg., Roof, Roof Penetration Mastic

Lab ID-Version 15338427-1

Sample Layers	Asbestos Content	
Black Roofing Mastic	ND	
Sample Composite Homogeneity:	Good	

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

 $\ddagger$  A "Version" indicated by -"x" after the Lab ID# with a value greater than 1 indicates a sample with amended data. The revision number is reflected by the value of "x".

# **Eurofins EPK Built Environment Testing, LLC**

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (866) 888-6653 www.eurofinsus.com/Built

Lab ID-Version 15338428-1

Client: A-Tech Consulting, Inc C/O: Mr. Robert Williams Date of Receipt: 02-17-2023 Re: 230586; 25001 Veterans Way Missions Viejo CADate of Report: 02-20-2023

#### ASBESTOS PLM REPORT

Location: 230586-A-007C, Bldg. 300, Roof, Northwest Bldg., Roof, Roof Penetration Mastic

Sample Layers	Asbestos Content
Black Roofing Mastic	ND
Sample Composite Homogeneity:	Good

#### Location: 230586-A-008A, Bldg. 300, Roof, Northwest Bldg., Roof, Flashing Mastic Lab ID-Version 1: 15338429-1

Sample Layers	Asbestos Content
White Roofing Mastic	ND
Composite Non-Asbestos Content:	3% Synthetic Fibers
Sample Composite Homogeneity:	Good

#### Location: 230586-A-008B, Bldg. 300, Roof, Northwest Bldg., Roof, Flashing Mastic Lab ID-Version:: 15338430-1

Sample Layers	Asbestos Content
White Roofing Mastic	ND
Composite Non-Asbestos Content:	3% Synthetic Fibers
Sample Composite Homogeneity:	Good

Location: 230586-A-008C, Bldg. 300, Roof, Northwest Bldg	., Roof, Flashing Mastic	Lab ID-Version <sup>‡</sup> : 15338431-1
--	--------------------------	--

Sample Layers	Asbestos Content
White Roofing Mastic	ND
Composite Non-Asbestos Content:	3% Synthetic Fibers
Sample Composite Homogeneity:	Good

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

A "Version" indicated by -"x" after the Lab ID# with a value greater than 1 indicates a sample with amended data. The revision number is reflected by the value of "x".



.

PLM BULK SAMPLE CHAIN OF CUSTODY			a and a set of the little of		
		Phone Number: (714) 434-636	50		
		Fax Number: (714) 221-6360	0031	70054	
		Attn: Robert Williams			
		Results: Email to labs@atechin	ic.net		
Project Number an	d Name:	Sampled By:			
230586 - Capistrano	Unified School District Newhart Middle School	Lloyd Tangunan			
Project Address:		City:	State:	Zip	:
25001 Veterans Way	Ý	Mission Viejo	CA	926	92-2735
Sample ID	Sample Location	Material	Friability	Condition	Est. Quantity
230586-A-001A	300, Roof, Southeast Bldg., Roof	Build-up Roofing Core	Non-Friable	Intact	2,000 SF
230586-A-001B	300, Roof, Southeast Bldg., Roof	Build-up Roofing Core	Non-Friable	Intact	Sec 001A
230586-A-001C	300, Roof, Southeast Bldg., Roof	Build-up Roofing Core	Non-Friable	Intact	See 001A
230586-A-001D	300, Roof, Southeast Bldg., Roof	Build-up Roofing Core	Non-Friable	Intact	See 001A
230586-A-001E	300, Roof, Southeast Bldg., Roof	Build-up Roofing Core	Non-Friable	Intact	See 001A
230586-A-002A	Bldg. 300, Roof, Southeast Bldg., Roof	Parapet Wall - Build-up Roofin	g Non-Friable	Intact	240 SF
230586-A-002B	Bldg. 300, Roof, Southeast Bldg., Roof	Parapet Wall - Build-up Roofin	g Non-Friable	Intact	See 002A
230586-A-002C	Bldg. 300, Roof, Southeast Bldg., Roof	Parapet Wall - Build-up Roofin	g Non-Friable	Intact	Sec 002A
230586-A-003A	Bldg. 300, Roof, Southcast Bldg., Roof	Roof Penetration Mastic	Non-Friable	Intact	75 SF
230586-A-003B	Bldg. 300, Roof, Southeast Bldg., Roof	Roof Penetration Mastic	Non-Friable	Intact	See 003A
230586-A-003C	Bldg, 300, Roof, Southeast Bldg., Roof	Roof Penetration Mastic	Non-Friable	Intact	Sec 003A
230586-A-004A	Bldg, 300, Roof, Southeast Bldg., Roof	Flashing Mastic	Non-Friable	Intact	10 SF
		Flashing Mastic	Non-Friable	Intact	Sec 004A

Client Sample Number: 230586-A-001A to 2	30586-A-008C	Total: 28
Relinquished By: ZHIJ	Lloyd Tangunan Date: 2/17/2023	Time: 1:05 AM
Samples Received By:	hotang Date: 2/17/2	5 Time: Jam
Relinquished By:	Date:	Time:
Samples Received By:	Date:	Time:

1640 North Batavia Street, Orange, CA 92867-3509 Phone: (714) 434-6360 Fax (714) 221-6360 Web Address: <u>www.atechine.net</u>

Chain of Custody

Page 1 of 2





#### PLM BULK SAMPLE CHAIN OF CUSTODY

230586-A-004C	Bldg. 300, Roof, Southeast Bldg., Roof	Flashing Mastic	Non-Friable	Intact	See 004A
230586-A-005A	Bldg. 300, Roof, Northwest Bldg., Roof	Build-up Roofing Core	Non-Friable	Intact	2,000 SF
230586-A-005B	Bldg. 300, Roof, Northwest Bldg., Roof	Build-up Roofing Core	Non-Friable	Intact	See 005A
230586-A-005C	Bldg, 300, Roof, Northwest Bldg., Roof	Build-up Roofing Core	Non-Friable	Intact	See 005A
230586-A-005D	Bldg, 300, Roof, Northwest Bldg., Roof	Build-up Roofing Core	Non-Friable	Intact	Sec 005A
230586-A-005E	Bldg. 300, Roof, Northwest Bldg., Roof	Build-up Roofing Core	Non-Friable	Intact	Sec 005A
230586-А-006А	Bldg. 300, Roof, Northwest Bldg., Roof	Parapet Wall - Build-up Roofing	Non-Friable	Intact	240 SF
230586-A-006B	Bldg. 300, Roof, Northwest Bldg., Roof	Parapet Wall - Build-up Roofing	Non-Friable	Intact	Sec 006A
230586-A-006C	Bldg. 300, Roof, Northwest Bldg., Roof	Parapet Wall - Build-up Roofing	Non-Friable	Intact	Sec 006A
230586-A-007A	Bldg. 300, Roof, Northwest Bldg., Roof	Roof Penetration Mastic	Non-Friable	Intact	70 SF
230586-A-007B	Bldg. 300, Roof, Northwest Bldg., Roof	Roof Penetration Mastic	Non-Friable	Intact	Sec 007A
230586-A-007C	Bldg. 300, Roof, Northwest Bldg., Roof	Roof Penetration Mastic	Non-Friable	Intact	Sec 007A
230586-A-008A	Bldg. 300, Roof, Northwest Bldg., Roof	Flashing Mastic	Non-Friable	Intact	10 SF
230586-A-008B	Bldg. 300, Roof, Northwest Bldg., Roof	Flashing Mastic	Non-Friable	Intact	See 008A
230586-A-008C	Bldg, 300, Roof, Northwest Bldg., Roof	Flashing Mastic	Non-Friable	Intact	Sec 008A

Client Sample Number: 230586-A-001A to 230586-A-008C				Total: 2
Relinquished By:	4700	Lloyd Tangunan	Date: 2/17/2023	Time: 1:05 AM
Samples Received By:	M	Sohntaing	Date: 2/17/23	Time: 8am
Samples Received Djr	- M	2-1411 4		

Date:

Date:

Relinquished By:

Samples Received By:

1640 North Batavia Street, Orange, CA 92867-3509 Phone: (714) 434-6360 Fax (714) 221-6360 Web Address: www.atechine.net

Time:

Time:

Chain of Custody

Page 2 of 2



